

DA20-C1 BOLDFACE

ABORT
THROTTLE — IDLE BRAKES — AS REQUIRED FLAPS — CRUISE
ENGINE MALFUNCTION — SUFFICIENT RUNWAY REMAINING TO LAND
AIRSPEED — 60 KIAS FLAPS — LDG
FUEL PRESSURE LOSS
FUEL PUMP — ON
ENGINE FIRE IN FLIGHT
FUEL SHUTOFF VALVE — OFF CABIN HEAT — OFF
ENGINE FIRE ON THE GROUND
FUEL SHUTOFF VALVE — OFF CABIN HEAT — OFF
ELECTRICAL FIRE ON THE GROUND
GEN/BAT MASTER SWITCH — OFF
ELECTRICAL FIRE IN FLIGHT
GEN/BAT MASTER SWITCH — OFF AIR VENTS AND WINDOWS — OPEN
CABIN FIRE IN FLIGHT
GEN/BAT MASTER SWITCH — OFF AIR VENTS AND WINDOWS — OPEN CABIN HEAT — OFF